

Instrumentation and Controls

ETM 3301

Lecture 14

Instructor

Dr. Farbod Khoshnoud

Routh Table

$$CE : a_4s^4 + a_3s^3 + a_2s^2 + a_1s + a_0 = 0$$

s^4	a_4	a_2	a_0
s^3	a_3	a_1	0
s^2	$-\frac{\begin{vmatrix} a_4 & a_2 \\ a_3 & a_1 \end{vmatrix}}{a_3} = b_1$	$-\frac{\begin{vmatrix} a_4 & a_0 \\ a_3 & 0 \end{vmatrix}}{a_3} = b_2$	0
s^1	$-\frac{\begin{vmatrix} a_3 & a_1 \\ b_1 & b_2 \end{vmatrix}}{b_1} = c_1$	$-\frac{\begin{vmatrix} a_3 & 0 \\ b_1 & 0 \end{vmatrix}}{b_1} = 0$	0
s^0	$-\frac{\begin{vmatrix} b_1 & b_2 \\ c_1 & 0 \end{vmatrix}}{c_1} = d_1$	$-\frac{\begin{vmatrix} b_1 & 0 \\ c_1 & 0 \end{vmatrix}}{c_1} = 0$	0

Example:

$$CE : s^4 + 5s^3 + 7s^2 + 3s + 5 = 0$$

s^4	1	7	5		+
s^3	5	3	0		+
s^2	$\frac{5 \times 7 - 1 \times 3}{5}$ = 6.4	$\frac{5 \times 5 - 1 \times 0}{5}$ = 5	0		+
s^1	$\frac{6.4 \times 3 - 5 \times 5}{6.4}$ = -0.9	0	0		-
s^0	$\frac{-0.9 \times 5 - 6.4 \times 0}{-0.9}$ = 5	0	0		+

Example:

$$CE : s^4 + 5s^3 + 7s^2 + 3s + 5 = 0$$

There are two changes in sign (+ to - and - to +) in the first column, hence the system is unstable and there are two poles with positive real parts.

Verification:

Poles are: $-2.55 \pm 0.546j,$

$$0.055 \pm 0.854j$$

Unstable system

Routh Table: Special Case I

- If the 1st element in a row is zero, it is replaced by a very small positive number ε , and the sign changes when $\varepsilon \rightarrow 0$ are counted after completing the array.

Example: $CE : s^5 + 2s^4 + 3s^3 + 6s^2 + 5s + 3 = 0$

s^5	1	3	5
s^4	2	6	3
s^3	$0 \longrightarrow \varepsilon$	3.5	0
s^2	$\frac{6\varepsilon - 7}{\varepsilon}$	3	0
s^1	$\frac{42\varepsilon - 49 - 6\varepsilon^2}{12\varepsilon - 14}$	0	0
s^0	3	0	0

Example: $CE : s^5 + 2s^4 + 3s^3 + 6s^2 + 5s + 3 = 0$

	$\varepsilon \rightarrow 0$	sign
s^5	1	+
s^4	2	+
s^3	ε	+
s^2	$-\infty$	-
s^1	49/14	+
s^0	3	+

Two sign changes.

Two poles with positive real parts.

$$0.343 \pm 1.508j$$

$$-1.67$$

$$-0.51 \pm 0.7j$$


Unstable system

Routh Table: Special Case II

- If all the elements in a row are zero, the system has poles with positive or zero real parts.
 - The system is either unstable or critically stable.
 - Need other methods to check stability.

Routh-Hurwitz Stability Criterion

- Check the system stability.
- Find the number of poles with positive real part.
- An important application of Routh-Hurwitz stability criterion is to find critical values of certain parameters in a control system for ensuring stability.




$K=4$, poles: $-0.102 \pm 1.192j$, -2.796 , stable

$K=10$, poles: $0.155 \pm 1.732j$, -3.309 , unstable

Example

- Find the range of K where the following system is stable.



Closed loop transfer function:

$$T(s) = \frac{Y(s)}{U(s)} = \frac{G(s)}{1 + G(s)} = \frac{K}{s(s+1)(s+2) + K}$$

CE:

$$s(s+1)(s+2) + K = 0$$

or $s^3 + 3s^2 + 2s + K = 0$

Example: Routh Table

$$CE : s^3 + 3s^2 + 2s + K = 0$$


s^3	1	2	0
s^2	3	K	0
s^1	$\frac{-\begin{vmatrix} 1 & 2 \\ 3 & K \end{vmatrix}}{3} = \frac{6-K}{3} = a$	$\frac{-\begin{vmatrix} 1 & 0 \\ 3 & 0 \end{vmatrix}}{3} = 0$	0
s^0	$\frac{-\begin{vmatrix} 3 & K \\ a & 0 \end{vmatrix}}{a} = K$	0	0

Stability Condition:

$$\left. \begin{array}{l} \frac{6-K}{3} > 0 \\ K > 0 \end{array} \right\} \Rightarrow 0 < K < 6$$

Example

- For what values of gain K , if any, is the system show below stable?



Closed loop transfer function:

$$T(s) = \frac{G(s)}{1 + G(s)H(s)} = \frac{K(s+10)}{s^3 + 14s^2 + 35s + (10K - 50)}$$

CE: $s^3 + 14s^2 + 35s + (10K - 50) = 0$

Routh Table

$$CE : s^3 + 14s^2 + 35s + (10K - 50) = 0$$

s^3	1	35	0
s^2	14	$10K-50$	0
s^1	$\frac{14 \times 35 - (10K - 50)}{14}$	0	0
s^0	$10K-50$	0	0

The system is stable if and only if:

$$\left. \begin{array}{l} \frac{14 \times 35 - (10K - 50)}{14} > 0 \\ 10K - 50 > 0 \end{array} \right\} \Rightarrow \left. \begin{array}{l} 490 > 10K - 50 \\ 10K > 50 \end{array} \right\} \Rightarrow 5 < K < 54$$